3M Center St. Paul, Minnesota 55144-1000 (612) 733-1110

6108

ABBREVIATIONS:

MATERIAL SAFETY DATA SHEET



ADHESIVES, COATINGS AND SEALERS DIVISION:

TRADE NAME: JET-MELT(R) Brand Adhesive 3762

3M I.D. NUMBER: 62-3762-7230-8 62-3762-7231-6 62-3762-7232-4 62-3762-7233-2 62-3762-9130-8 62-3762-9530-9 62-3762-9630-7 62-3762-9730-5 62-3762-9930-1

ISSUED: DECEMBER 9, 1985 SUPERSEDES: OCTOBER 3, 1985

DOCUMENT: 10-0381-3

EXPOSURE

1. INGREDIENTS	C.A.S. NO.	PERCENT	LIMITS	
Ethylene vinyl acetate resin	N/A		N/D	5
Hydrocarbon resin	N/A		N/D	5
Hydrocarbon wax				5
TOTAL OF THE ABOVE	N/A	100.0	N/D	5

SOURCE OF EXPOSURE LIMIT DATA:

 ACGIH Threshold Limit Values
Federal OSHA Permissible Exposure Limit N/D - Not Determined N/A - Not Applicable

3M Exposure Guidelines
Chemical Manufacturer Recommended Guidelines
None Established

2. PHYSICAL DATA

pH:

BOILING POINT: N/A **VAPOR PRESSURE:** N/A VAPOR DENSITY (Air=1): N/A EVAPORATION RATE (Ether=1): N/A APPEARANCE AND ODOR: Solid - tan Insoluble SOLUBILITY IN WATER: SP. GRAVITY (Water=1): 0.95 PERCENT VOLATILE: 0 N/A VISCOSITY:

N/A

3M Center St. Paul, Minnesota 55144-1000 (612) 733-1110

MATERIAL SAFETY DATA SHEET

IF SWALLOWED:

No toxic effects expected. Call a physician.



MSDS: JET-MELT(R) Brand Adhesive 3762 Page 2 DECEMBER 9, 1985 ______ 3. FIRE AND EXPLOSION HAZARD DATA FLASH POINT ((0.C.) ASTM D-92-72): 500F FLAMMABLE LIMITS - LEL: N/A UEL: N/A EXTINGUISHING MEDIA: CO2, foam, water, dry chemical SPECIAL FIRE FIGHTING PROCEDURES: Fire fighters should wear self-contained breathing apparatus when fighting fires involving this material. UNUSUAL FIRE AND EXPLOSION HAZARDS: None 4. REACTIVITY DATA _____ STABILITY: STABLE INCOMPATIBILITY - MATERIALS TO AVOID: HAZARDOUS POLYMERIZATION: MAY NOT OCCUR HAZARDOUS DECOMPOSITION PRODUCTS: CO, CO2, and smoke particles when subjected to excessive heat or flame. 5. ENVIRONMENTAL INFORMATION SPILL RESPONSE: N/A RECOMMENDED DISPOSAL: Product may be disposed of as ordinary non-hazardous solid waste. **ENVIRONMENTAL DATA:** N/D 6. SUGGESTED FIRST AID _______ EYE CONTACT: Vapor of heated resin: Immediately flush eyes with plenty of water for at least 10 minutes. Call a physician. SKIN CONTACT: No hazard at room temperature. Hot adhesive: Flush skin immediately with cold water and cover with a clean dressing. DO NOT ATTEMPT TO REMOVE ADHESIVE. Call a physician. INHALATION: No toxic effects expected. Provide fresh air.

3M Center St. Paul, Minnesota 55144-1000 (612) 733-1110

MATERIAL SAFETY DATA SHEET



MSDS: JET-MELT(R) Brand Adhesive 3762 DECEMBER 9, 1985 Page 3

7. PRECAUTIONARY INFORMATION

Avoid contact with hot extruded adhesive or applicator tip. Avoid prolonged breathing of vapors of heated adhesive.

3M Center St. Paul, Minnesota 55144-1000 (612) 733-1110

MATERIAL SAFETY DATA SHEET



MSDS: JET-MELT(R) Brand Adhesive 3762 DECEMBER 9, 1985 Page 4

8. HEALTH HAZARD DATA

EYE CONTACT: Vapors of heated resin may cause irritation.

SKIN CONTACT: Hot adhesives will burn skin. Prolonged or repeated contact may cause mild skin irritation.

INHALATION: Not applicable at room temperature. Vapors of hot adhesive may be irritating to the nose and throat.

INGESTION: Practically non-toxic.

The information on this Data Sheet represents our current data and best opinion as to the proper use in handling of this product under normal conditions. Any use of the product which is not in conformance with this Data Sheet or which involves using the product in combination with any other product or any other process is the responsibility of the user.